


If oil supply of elevator guide rail is excessive...








Installation effect of guide rail oiler - Flat oiler


Oil adjustment is not necessary

Extra strong new material has been adopted in the friction part of oil retaining material.



Saves oil

Economical, compared to conventional model. Replenishing is not necessary for more than a year, with only 300cm³.



No oil scattering

Oil does not scatter above the elevator cage and within the shaft. Therefore, there are no oil stains on the observation elevator and elevator crime preventive window glass.



Reduces maintenance time

Replenishing frequency is reduced.



Small waste oil discharge count

Not much waste oil is accumulated in the pit, and there is a remarkably small discharge (collection).

